



PARTSCAP




ALLIANCE PARTS



Click Here to Download 28" W x 19" Tall Wall Chart (<https://aae-img.s3.us-east-2.amazonaws.com/OET/pdf/Alliance%20Heavy%20Duty%20Wall%20Chart%20ABP%20N83%20MT9280.pdf>)





Alliance ABP N83 MT9280 A/C Rapid Repair Kit

Product Features and Benefits

FEATURES

- Medium and Heavy Duty Truck Coverage 2022-2010
- Most Commonly Used A/C Small Parts on Medium and Heavy Duty Trucks
- Kit in Kit - Color Codes Sections to Organize Components for easy identification
- R134a and R1234yf Systems
- Coverage includes Navistar, Mack, Freightliner, Peterbilt, Ford/Sterling GM/Volvo, Sprinter Van, Dodge, Mercedes

HIGHLIGHTS



-
- Box 1 - ABP N83 MT9665 Compressor Ports & Line Connection O-Rings
 - Box 2 - ABP N83 MT9666 Sealing Washers HD Trucks and O_Rings Sprinter Van
 - Box 3 - ABP N83 MT9628 Caps, Valve Cores, and Service Ports
 - Box 4 - ABPN83 MT9663 Orifice Tubes and Orifice Tube Repair Kit
 - Individual packs for replenishment available via Direct Ship. See attached spreadsheet with pack sizes

A/C Rapid Repair Kit - Sales Sheet

Rapid Repair Kit - Individual Pieces and Pack Sizes

Last updated: Tuesday, 28 November 2023 05:50 PM

[^Back to Top](#)

Copyright © Daimler Truck North America LLC. [Privacy Statement, Legal Notices and Terms \(https://daimler-trucksnorthamerica.com/privacy-policy\)](https://daimler-trucksnorthamerica.com/privacy-policy).

All rights reserved. Daimler Truck North America LLC is a [Daimler \(http://www.daimler.com/\)](http://www.daimler.com/) company.

