

FAN CLUTCH REPAIR KITS

CROSS REFERENCE

Alliance™ Parts	Kit Master Kit	Horton Quick Kit	Horton Super Kit	
ABP N20 795568N	14-256	Q995568	995530	
	14-256	N/A	995567	
	14-500	N/A	995607	
	14-500	N/A	995608	
	14-256	Q995568	995568	
	14-256	Q995575	995575	
ABP N20 795669	14-256-1	Q995669	994353 - OBSOL	
	14-256-1	Q995669	995669	
ABP N20 795582	24-256	Q995582	995582	
	24-256	N/A	995543	
	24-256	Q995617	995617	
	24-256	Q995617-L	N/A	
	24-256	N/A	995547	
Total # of Part #'s to support market	3	4	6	11

Alliance™ Parts	Kit Masters	Horton
ABP N20 4205	4205	994370
ABP N20 9500HP	9500HP	994305
ABP N20 7500HP	7500HP	994307
ABP N20 795568N	14-256, 14-500	995568, Q995568, Q995575, 995530, 995567, 995607, 995608, 995575
ABP N20 795669	14-256-1	Q995669, 995669
ABP N20 795582	24-256	995582, Q995582, 995543, 995617, 995547, Q995617, Q995617-L
ABP N20 9908504	8801X, 8801N, 8901N, 8905N, 1090-09650-01, 1090-09750-01	9908504



WHEN A COMPLETE FAN DRIVE ASSEMBLY IS NOT AVAILABLE AND YOU NEED TO SAVE MONEY ON ALL MAKES, USE ALLIANCE™ PARTS REPAIR KITS.